



# 석면비산 측정 결과보고서



주식회사 에이앤환경

광주지방고용노동청 제2017-120003호





[별첨 2] 평사리 1176-11 ※작업시간 3시간  
 ★측정 지점 위치도(도식도) [2019년 12월 27일]



[별첨 3] 평사리 1176-11 ※작업시간 3시간  
[2019년 12월 27일]

### 석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 09:00	측정종료시간 : 12:03	
#2 부지경계			
	측정시작시간 : 09:00	측정종료시간 : 12:03	
#3 부지경계			
	측정시작시간 : 09:00	측정종료시간 : 12:04	
#4 부지경계			
	측정시작시간 : 09:00	측정종료시간 : 12:04	
#5 부지경계			
	측정시작시간 : 09:30	측정종료시간 : 10:05	

[별첨 3] 평사리 1176-11 ※작업시간 3시간  
 [2019년 07월 26일]

**석면비산 농도측정 관련 사진**

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 음압기 배출구	 측정시작시간 : 09:30	 측정종료시간 : 10:05	
#7 폐기물 반출구	 측정시작시간 : 10:10	 측정종료시간 : 10:46	



[별첨 2] 덕은리 622-1, 덕은리 816-47, 덕은리 820-1 ※작업시간 3시간  
★측정 지점 위치도(도식도) [2019년 12월 27일]




### 덕은리 622-1, 816-47, 820-1





[별첨 3] 덕은리 622-1, 덕은리 816-47, 덕은리 820-1 ※작업시간 3시간  
[2019년 12월 27일]

### 석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 11:30	측정종료시간 : 14:32	
#2 부지경계			
	측정시작시간 : 11:33	측정종료시간 : 14:36	
#3 부지경계			
	측정시작시간 : 11:35	측정종료시간 : 14:39	
#4 부지경계			
	측정시작시간 : 11:37	측정종료시간 : 14:43	
#5 부지경계			
	측정시작시간 : 12:19	측정종료시간 : 12:55	

[별첨 3] 덕은리 622-1, 덕은리 816-47, 덕은리 820-1 ※작업시간 3시간  
 [2019년 12월 27일]

**석면비산 농도측정 관련 사진**

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 음압기 배출구			
	측정시작시간 : 12:20	측정종료시간 : 12:55	
#7 작업장 주변 (실외)			
	측정시작시간 : 12:40	측정종료시간 : 14:25	
#8 폐기물 반출구			
	측정시작시간 : 12:50	측정종료시간 : 13:27	
#9 폐기물 반출구			
	측정시작시간 : 12:55	측정종료시간 : 13:31	
#10 폐기물 보관지점			
	측정시작시간 : 14:35	측정종료시간 : 15:10	

[별첨 3] 덕은리 622-1, 덕은리 816-47, 덕은리 820-1 ※작업시간 3시간  
 [2019년 12월 27일]

### 석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#11 폐기물 보관지점	 측정시작시간 : 14:35	 측정종료시간 : 15:10	
#12 폐기물 보관지점	 측정시작시간 : 14:40	 측정종료시간 : 15:16	
#13 폐기물 보관지점	 측정시작시간 : 14:40	 측정종료시간 : 15:16	